


SOLUTIONS TO STATIC PROBLEMS

PACKAGING VERTICAL FORM FILL PACKAGING MACHINES

Static electricity on the film attracts the product which causes bad sealing on the top and bottom of the bags. This is a common problem with light and dusty products.




A 1250-S Bar here, just before the metal shoulder will neutralise the inside of the film / bag. The bar must be before the shoulder, not over it.

Filling Tube

Position 2 x 1250-S Static Eliminator Bars just below the filling tube - Important: it must be below the tube—and 20mm away from the film.

The 1250-S Bars should be just above the top position of the horizontal sealer.



Vertical form filling of liquids requires the same equipment solution.